

close

Download

Performance Graph

The performance graph plots three variables against Torque (Nm) on the x-axis (0.00 to 8.00 Nm). The left y-axis shows Speed (RPM) from 0 to 40 and Efficiency (%) from 0 to 100. The right y-axis shows Current (A) from 0.0 to 3.0. The black curve represents Speed, which decreases from approximately 28 RPM at 1.0 Nm to 10 RPM at 5.0 Nm. The red curve represents Efficiency, which increases from approximately 18% at 1.0 Nm to 25% at 5.0 Nm. The green curve represents Current, which peaks at approximately 12 A around 3.5 Nm and then decreases to about 5 A at 5.0 Nm.